MONTHLY NOTAM SUMMARY

DIRECTLINE: +260211271048 MOBILE: +260967980776 AFTN: FLKKYNYX EMAIL:ais.lusaka@zacl.aero WEBSITE: www.zacl.co.zm	**INTERNATIONAL NOTAM OFFICE ZAMBIA AIRPORTS CORPORATION LIMITED P.O. BOX 30175, LUSAKA ZAMBIA**	NOTAM LIST SERIES C **November 2018** ZACL/KKIA/3.3/2.8C

The following NOTAMs Series (C) are still enforce for November 2018. NOTAMs not included in the list have been cancelled, time expired or superseded by AIP supplement.

CHECKLIST OF SERIES (C)

YEAR=2007 0008 0009 0010
YEAR=2010 0014
YEAR=2011 0017
YEAR=2012 0002
YEAR=2015 0010 0012
YEAR=2017 0010 0018
YEAR=2018 0016

LUSAKA FIR (FLFI)		
C0008/07	16-06-07 Permanently, Siandunda Microlight aerodrome now licensed and operational. GPS coordinates 174741.1S 0243731.4E, elevation 1007m. Operator Livingstone Tobacco farm P.O Box 60301 Livingstone Tel/+26095591566881 0r +260978545337.	**SIANDUNDA MICROLIGHT**
C0009/07	16-06-07 Bimbi helipad licensed and operational.GPS coordinates 180109.1S 0264436.8E elevation 519m.Operator Maunga Fishing and Safaris Limited P.O.Box 6 Zimba Tel2603324390.	**BIMBI HELIPAD**
C0010/07	16-06-07 Permanently, Bimbi Microlight aerodrome now licensed. GPS coordinates 180117.4S 0264439.8E elevation 480m. Operator Maunga Fishing Safaries Limited P.O Box 6, Zimba Tel/+260213324390.	**BIMBI MICROLIGHT**

C0014/10	31-08-10 Permanently, Masebe AIRSTRIP IN MKUSHI COORDINATES s134647.8E 01291758.5 resumed normal operation.	**MASEBE AIRSTRIP**
C0017/11	31-08-11 Permanently, Lilayi airstrip closed.	**LILAYI AIRSTRIP**
C0002/12	16-01-12 Permanently, Kapamba airfield coordinates 132200S0313400E, operated by Mfuwe Trails Zambia Limited.	**KAPAMBA AIRFIELD**
C0010/15	18-06-15 Permanently, Landing at city airport after 1500 UTC using RWY26 is restricted.	**LUSAKA CITY AIRPORT (FLLC)**
C0012/15	14-07-15 Permanently, KULEFU AERODROME LOCATION: S153628.3E0294818.6 RWY HDG: 09/27 RWY Length :900M RWY WIDITH: 30M Strip Dimensions: 1000X90M STS: Serviceable. Pilots to be warned that there is a Gulley at the end of RWY 09 overrun (just after 100 Meters from the displaced threshold markings).	**KULEFU AERODROME**
C0010/17	08-05-17 Permanently, There are power lines in the approach path on the southwest end of the runway 06/24. The power lines are about 12metres high and 150meters away from the threshold. Pilots to exercise caution.	**NKAMBA BAY**
C0018/17	28-08-17 Permanently, RWY 21 at Mukinge Aerodrome has ZESCO power lines in the Approach path about 20Metres from the runway over run. Coordinates: 132838.8S 0255121.4E, Elevation 122metres. Pilots to exercise caution when landing.	**MUKINGE AERODROME**
C0016/18	17-09-18 until 17-12-18 Aerodrome closed due to work in progress.	**KASABA BAY AERODROME**
AIP Amendment	**001/2008**	
AIRAC AIP Supplement	**002/2017**	
AIP Supplement	**005/2018**	
AIC Series A	**0010/2018**	
AIC Series B	**001/2018**	

Checklist of AIP Suppléments in force	
YEAR=2004	001
YEAR=2010	001 005
YEAR=2011	002
YEAR=2013	003
YEAR=2014	002 003 004 005
YEAR=2015	002 005 006
YEAR=2016	004
YEAR=2017	001 002
YEAR=2018	001 002 003 004 005
Checklist of AIRAC AIP Suppléments in force	
YEAR=2017	002

NOTE : NEXT AIRAC EFFECTIVE DATE 6th DECEMBER 2018, NIL NOTIFICATION

Iven B Mwenya
Senior Aeronautical Information Services Officer (SAISO**).**