


MONTHLY NOTAM SUMMARY

 DIRECTLINE: +260211271048 MOBILE: +260967980776 AFTN: FLKKYNYX EMAIL: ais.lusaka@zacl.aero WEBSITE: www.zacl.co.zm	INTERNATIONAL NOTAM OFFICE ZAMBIA AIRPORTS CORPORATION LIMITED P.O. BOX 30175, LUSAKA ZAMBIA	NOTAM LIST SERIES C <u>February 2019</u> ZACL/KKIA/3.3/2.8C
---	---	---

The following NOTAMs Series (C) are still enforce for February 2019. NOTAMs not included in the list have been cancelled, time expired or superseded by AIP supplement.

CHECKLIST OF SERIES (C)

YEAR=2007 0008 0009 0010
YEAR=2010 0014
YEAR=2011 0017
YEAR=2012 0002
YEAR=2015 0010 0012
YEAR=2017 0010 0018
YEAR=2018 0021

LUSAKA FIR (FLFI)		
C0008/07	16-06-07 Permanently, Siandunda Microlight aerodrome now licensed and operational. GPS coordinates 174741.1S 0243731.4E, elevation 1007m. Operator Livingstone Tobacco farm P.O Box 60301 Livingstone Tel/+26095591566881 Or +260978545337.	SIANDUNDA MICROLIGHT
C0009/07	16-06-07 Bimbi helipad licensed and operational. GPS coordinates 180109.1S 0264436.8E elevation 519m. Operator Maunga Fishing and Safaris Limited P.O.Box 6 Zimba Tel2603324390.	BIMBI HELIPAD
C0010/07	16-06-07 Permanently, Bimbi Microlight aerodrome now licensed. GPS coordinates 180117.4S 0264439.8E elevation 480m. Operator Maunga Fishing Safaries Limited P.O Box 6, Zimba Tel/+260213324390.	BIMBI MICROLIGHT

MONTHLY NOTAM SUMMARY

C0014/10	31-08-10 Permanently, Masebe AIRSTRIP IN MKUSHI COORDINATES s134647.8E 01291758.5 resumed normal operation.	MASEBE AIRSTRIP
C0017/11	31-08-11 Permanently, Lilayi Airstrip closed.	LILAYI AIRSTRIP
C0002/12	16-01-12 Permanently, Kapamba Airfield coordinates 132200S0313400E, operated by Mfuwe Trails Zambia Limited.	KAPAMBA AIRFIELD
C0010/15	18-06-15 Permanently, Landing at city airport after 1500 UTC using RWY26 is restricted.	LUSAKA CITY AIRPORT (FLLC)
C0012/15	14-07-15 Permanently, KULEFU AERODROME LOCATION: S153628.3E0294818.6 RWY HDG: 09/27 RWY Length :900M RWY WIDTH: 30M Strip Dimensions: 1000X90M STS: Serviceable. Pilots to be warned that there is a Gulley at the end of RWY 09 overrun (just after 100 Meters from the displaced threshold markings).	KULEFU AERODROME
C0010/17	08-05-17 Permanently, There are power lines in the approach path on the southwest end of the runway 06/24. The power lines are about 12metres high and 150meters away from the threshold. Pilots to exercise caution.	NKAMBA BAY
C0018/17	28-08-17 Permanently, RWY 21 at Mukinge Aerodrome has ZESCO power lines in the Approach path about 20Metres from the runway over run. Coordinates: 132838.8S 0255121.4E, Elevation 122metres. Pilots to exercise caution when landing.	MUKINGE AERODROME
C0021/18	18-12-18 until 17-03-19 Aerodrome closed due to work in progress.	KASABA BAY AERODROME
AIP Amendment 001/2008 AIRAC AIP Supplement 002/2017 AIP Supplement 005/2018 AIC Series A 0010/2018 AIC Series B 001/2018		

MONTHLY NOTAM SUMMARY

Checklist of AIP Suppléments in force	
YEAR=2004	001
YEAR=2010	001 005
YEAR=2011	002
YEAR=2013	003
YEAR=2014	002 003 004 005
YEAR=2015	002 005 006
YEAR=2016	004
YEAR=2017	001 002
YEAR=2018	001 002 003 004 005
Checklist of AIRAC AIP Suppléments in force	
YEAR=2017	002
YEAR=2018	001

NOTE : NEXT AIRAC EFFECTIVE DATE 28th FEBRAURY 2019, NIL NOTIFICATION

Iven B Mwenya
Senior Aeronautical Information Services Officer (SAISO).