


MONTHLY NOTAM SUMMARY

 <p>DIRECTLINE: +260211271048 MOBILE: +260967980776 AFTN: FLKKYNYX EMAIL: ais.lusaka@zacl.aero WEBSITE: www.zacl.co.zm</p>	<p>INTERNATIONAL NOTAM OFFICE ZAMBIA AIRPORTS CORPORATION LIMITED P.O. BOX 30175, LUSAKA ZAMBIA</p>	<p>NOTAM LIST SERIES C <u>June 2019</u> ZACL/KKIA/3.3/2.8C</p>
---	--	---

**The following NOTAMs Series (C) are still enforce for June 2019.
NOTAMs not included in the list have been cancelled, time
expired or superseded by AIP supplement.**

CHECKLIST OF SERIES (C)

YEAR=2007 0008 0009 0010
YEAR=2010 0014
YEAR=2011 0017
YEAR=2012 0002
YEAR=2015 0010 0012
YEAR=2017 0010 0018
YEAR=2019 0006

LUSAKA FIR (FLFI)		
C0008/07	16-06-07 Permanently, Siandunda Microlight aerodrome now licensed and operational. GPS coordinates 174741.1S 0243731.4E, elevation 1007m. Operator Livingstone Tobacco farm P.O Box 60301 Livingstone Tel/+26095591566881 Or +260978545337.	SIANDUNDA MICROLIGHT
C0009/07	16-06-07 Permanently, Bimbi Helipad licensed and operational. GPS coordinates 180109.1S 0264436.8E elevation 519m. Operator Maunda Fishing and Safaris Limited PO Box 6 Zimba tel/+2603324390.	BIMBI HELIPAD
C0010/07	16-06-07 Permanently, Bimbi Microlight aerodrome now licensed. GPS coordinates 180117.4S 0264439.8E elevation 480m. Operator Maunga Fishing Safaries Limited P.O Box 6, Zimba Tel/+260213324390.	BIMBI MICROLIGHT

MONTHLY NOTAM SUMMARY

C0014/10	31-08-10 Permanently, Masebe AIRSTRIP IN MKUSHI COORDINATES s134647.8E 01291758.5 resumed normal operation.	MASEBE AIRSTRIP
C0017/11	31-08-11 Permanently, Lilayi Airstrip closed.	LILAYI AIRSTRIP
C0002/12	16-01-12 Permanently, Kapamba Airfield coordinates 132200S0313400E, operated by Mfuwe Trails Zambia Limited.	KAPAMBA AIRFIELD
C0010/15	18-06-15 Permanently, Landing at city airport after 1500 UTC using RWY26 is restricted.	LUSAKA CITY AIRPORT (FLLC)
C0012/15	14-07-15 Permanently, KULEFU AERODROME LOCATION: S153628.3E0294818.6 RWY HDG: 09/27 RWY Length :900M RWY WIDTH: 30M Strip Dimensions: 1000X90M STS: Serviceable. Pilots to be warned that there is a Gulley at the end of RWY 09 overrun (just after 100 Meters from the displaced threshold markings).	KULEFU AERODROME
C0010/17	08-05-17 Permanently, There are power lines in the approach path on the southwest end of the runway 06/24. The power lines are about 12metres high and 150meters away from the threshold. Pilots to exercise caution.	NKAMBA BAY
C0018/17	28-08-17 Permanently, RWY 21 at Mukinge Aerodrome has ZESCO power lines in the Approach path about 20Metres from the runway over run. Coordinates: 132838.8S 0255121.4E, Elevation 122metres. Pilots to exercise caution when landing.	MUKINGE AERODROME
C0006/19	20-03-19 until 20-06-19 Aerodrome closed due to work in progress.	KASABA BAY AERODROME
AIP Amendment 001/2008 AIRAC AIP Supplement 001/2019 AIRAC AIP Supplement 002/2019 AIP Supplement 005/2018 AIC Series A 002/2019 AIC Series B 001/2018		

MONTHLY NOTAM SUMMARY

Checklist of AIP Suppléments in force	
YEAR=2004	001
YEAR=2010	004 005
YEAR=2011	002
YEAR=2013	003
YEAR=2014	002 003 004 005
YEAR=2015	002 005 006
YEAR=2016	002 003 004 007
YEAR=2017	001 002
YEAR=2018	001 003 004 005
Checklist of AIRAC AIP Suppléments in force	
YEAR=2017	002
YEAR=2018	001
YEAR=2019	001 002

NOTE : NEXT AIRAC EFFECTIVE DATE 20th JUNE2019, NIL NOTIFICATION

IVEN MWENYA

Senior Aeronautical Information Services Officer (SAISO).