


## MONTHLY NOTAM SUMMARY

 DIRECTLINE: +260211271048 MOBILE: +260967980776 AFTN: FLKKYNYX EMAIL: ais.lusaka@zacl.aero WEBSITE: <a href="http://www.zacl.co.zm">www.zacl.co.zm</a>	<b>INTERNATIONAL NOTAM OFFICE ZAMBIA AIRPORTS CORPORATION LIMITED P.O. BOX 30175, LUSAKA ZAMBIA</b>	NOTAM LIST SERIES C <b><u>July 2018</u></b> ZACL/KKIA/3.3/2.8C
---	---	---

-----  
**The following NOTAMs Series (C) are still enforce for July 2018.  
NOTAMs not included in the list have been cancelled, time  
expired or superseded by AIP supplement.**  
-----

### **CHECKLIST OF SERIES (C)**

YEAR=2007 0008 0009 0010  
YEAR=2010 0014  
YEAR=2011 0017  
YEAR=2012 0002  
YEAR=2015 0010 0012  
YEAR=2017 0010 0018  
YEAR=2018 0011

<b>LUSAKA FIR (FLFI)</b>		
<b>C0008/07</b>	16-06-07 Permanently, Siandunda Microlight aerodrome now licensed and operational. GPS coordinates 174741.1S 0243731.4E, elevation 1007m. Operator Livingstone Tobacco farm P.O Box 60301 Livingstone Tel/+26095591566881 Or +260978545337.	<b>SIANDUNDA MICROLIGHT</b>
<b>C0009/07</b>	16-06-07 Bimbi helipad licensed and operational. GPS coordinates 180109.1S 0264436.8E elevation 519m. Operator Maunga Fishing and Safaris Limited P.O.Box 6 Zimba Tel2603324390.	<b>BIMBI HELIPAD</b>
<b>C0010/07</b>	16-06-07 Permanently, Bimbi Microlight aerodrome now licensed. GPS coordinates 180117.4S 0264439.8E elevation 480m. Operator Maunga Fishing Safaries Limited P.O Box 6, Zimba Tel/+260213324390.	<b>BIMBI MICROLIGHT</b>

## MONTHLY NOTAM SUMMARY

<b>C0014/10</b>	31-08-10 Permanently, Masebe AIRSTRIP IN MKUSHI COORDINATES s134647.8E 01291758.5 resumed normal operation.	<b>MASEBE AIRSTRIP</b>
<b>C0017/11</b>	31-08-11 Permanently, Lilayi airstrip closed.	<b>LILAYI AIRSTRIP</b>
<b>C0002/12</b>	16-01-12 Permanently, Kapamba airfield coordinates 132200S0313400E, operated by Mfuwe Trails Zambia Limited.	<b>KAPAMBA AIRFIELD</b>
<b>C0010/15</b>	18-06-15 Permanently, Landing at city airport after 1500 UTC using RWY26 is restricted.	<b>LUSAKA CITY AIRPORT (FLLC)</b>
<b>C0012/15</b>	14-07-15 Permanently, KULEFU AERODROME LOCATION: S153628.3E0294818.6 RWY HDG: 09/27 RWY Length :900M RWY WIDTH: 30M Strip Dimensions: 1000X90M STS: Serviceable. Pilots to be warned that there is a Gulley at the end of RWY 09 overrun (just after 100 Meters from the displaced threshold markings).	<b>KULEFU AERODROME</b>
<b>C0010/17</b>	08-05-17 Permanently, There are power lines in the approach path on the southwest end of the runway 06/24. The power lines are about 12metres high and 150meters away from the threshold. Pilots to exercise caution.	<b>NKAMBA BAY</b>
<b>C0018/17</b>	28-08-17 Permanently, RWY 21 at Mukinge Aerodrome has ZESCO power lines in the Approach path about 20Metres from the runway over run. Coordinates: 132838.8S 0255121.4E, Elevation 122metres. Pilots to exercise caution when landing.	<b>MUKINGE AERODROME</b>
<b>C0011/18</b>	02-07-18 until 02-08-18 Aerodrome closed due to work in progress.	<b>KASABA BAY AERODROME</b>
<b>AIP Amendment 001/2008</b> <b>AIRAC AIP Supplement 002/2017</b> <b>AIP Supplement 002/2018</b> <b>AIC Series A 004 /2018</b>		

## MONTHLY NOTAM SUMMARY

---

<b>Checklist of AIP Suppléments in force</b>	
YEAR=2004	001
YEAR=2010	001 005
YEAR=2011	002
YEAR=2013	003
YEAR=2014	002 003 004 005
YEAR=2015	002 005 006
YEAR=2016	004
YEAR=2017	001 002
YEAR=2018	001 002
<b>Checklist of AIRAC AIP Suppléments in force</b>	
YEAR=2017	002

**NOTE : NEXT AIRAC EFFECTIVE DATE 19TH JULY 2018, NIL NOTIFICATION**

---

**Iven B Mwenya**  
**Senior Aeronautical Information Services Officer (SAISO).**