


# MONTHLY NOTAM SUMMARY

 <p style="font-size: small;">             DIRECTLINE: +260211271048              MOBILE: +260967980776              AFTN: FLKKYNYX              EMAIL: ais.lusaka@zacl.aero              WEBSITE: <a href="http://www.zacl.co.zm">www.zacl.co.zm</a> </p>	<p><b>INTERNATIONAL NOTAM OFFICE ZAMBIA AIRPORTS CORPORATION LIMITED P.O. BOX 30175, LUSAKA ZAMBIA</b></p>	<p style="text-align: center;">             NOTAM LIST              SERIES C  <u>March 2020</u>              ZACL/KKIA/3.3/2.8C         </p>
---	--	--

-----

**The following NOTAMs Series (C) are still enforce March 2020.  
NOTAMs not included in the list have been cancelled, time  
expired or superseded by AIP supplement.**

-----

### CHECKLIST OF SERIES (C)

YEAR=2007 0008 0009 0010  
 YEAR=2010 0014  
 YEAR=2011 0017  
 YEAR=2012 0002  
 YEAR=2015 0010 0012  
 YEAR=2017 0010 0018  
 YEAR=2019 0021  
 YEAR=2020 0002

LUSAKA FIR (FLFI)		
<b>C0008/07</b>	16-06-07 Permanently, Siandunda Microlight aerodrome now licensed and operational. GPS coordinates 174741.1S 0243731.4E, elevation 1007m. Operator Livingstone Tobacco farm P.O Box 60301 Livingstone Tel/+26095591566881 Or +260978545337.	<b>SIANDUNDA MICROLIGHT</b>
<b>C0009/07</b>	16-06-07 Bimbi helipad licensed and operational. GPS coordinates 180109.1S 0264436.8E elevation 519m. Operator Maunga Fishing and Safaris Limited P.O.Box 6 Zimba Tel2603324390.	<b>BIMBI HELIPAD</b>
<b>C0010/07</b>	16-06-07 Permanently, Bimbi Microlight aerodrome now licensed. GPS coordinates 180117.4S 0264439.8E elevation 480m. Operator Maunga Fishing Safaries Limited P.O Box 6, Zimba Tel/+260213324390.	<b>BIMBI MICROLIGHT</b>

## MONTHLY NOTAM SUMMARY

<b>C0014/10</b>	31-08-10 Permanently, Masebe AIRSTRIP IN MKUSHI COORDINATES s134647.8E 01291758.5 resumed normal operation.	<b>MASEBE AIRSTRIP</b>
<b>C0017/11</b>	31-08-11 Permanently, Lilayi Airstrip closed.	<b>LILAYI AIRSTRIP</b>
<b>C0002/12</b>	16-01-12 Permanently, Kapamba Airfield coordinates 132200S0313400E, operated by Mfuwe Trails Zambia Limited.	<b>KAPAMBA AIRFIELD</b>
<b>C0010/15</b>	18-06-15 Permanently, Landing at city airport after 1500 UTC using RWY26 is restricted.	<b>LUSAKA CITY AIRPORT (FLLC)</b>
<b>C0012/15</b>	14-07-15 Permanently, KULEFU AERODROME LOCATION: S153628.3E0294818.6 RWY HDG: 09/27 RWY Length :900M RWY WIDTH: 30M Strip Dimensions: 1000X90M STS: Serviceable. Pilots to be warned that there is a Gully at the end of RWY 09 overrun (just after 100 Meters from the displaced threshold markings).	<b>KULEFU AERODROME</b>
<b>C0010/17</b>	08-05-17 Permanently, There are power lines in the approach path on the southwest end of the runway 06/24. The power lines are about 12metres high and 150meters away from the threshold. Pilots to exercise caution.	<b>NKAMBA BAY</b>
<b>C0018/17</b>	28-08-17 Permanently, RWY 21 at Mukinge Aerodrome has ZESCO power lines in the Approach path about 20Metres from the runway over run. Coordinates: 132838.8S 0255121.4E, Elevation 122metres. Pilots to exercise caution when landing.	<b>MUKINGE AERODROME</b>
<b>C0021/19</b>	23-12-19 until 23-03-20 Aerodrome closed due to work in progress	<b>KASABA BAY AERODROME</b>
<b>C0002/20</b>	16-01-20 until 15-04-20 City Airport closed.	<b>CITY AIRPORT</b>
<b>AIP Amendment</b>	<b>001/2008</b>	
<b>AIRAC AIP Supplement</b>	<b>006/2020</b>	
<b>AIP Supplement</b>	<b>007/2020</b>	
<b>AIC Series A</b>	<b>004/2020</b>	
<b>AIC Series B</b>	<b>001/2018</b>	

## MONTHLY NOTAM SUMMARY

---

<b>Checklist of AIP Suppléments in force</b>	
YEAR=2004	001
YEAR=2010	004 005
YEAR=2011	002
YEAR=2013	003
YEAR=2014	002 003 004 005
YEAR=2015	002 005 006
YEAR=2016	002 003 004 007
YEAR=2017	001 002
YEAR=2018	001 003 004 005
YEAR=2020	001 002 003 004 005 006 007
<b>Checklist of AIRAC AIP Suppléments in force</b>	
YEAR=2017	002
YEAR=2018	001
YEAR=2019	001 002 003 004 005 006 007 008 009 010

**NOTE : NEXT AIRAC EFFECTIVE DATE 26th March 2020, NIL NOTIFICATION**

---

**Iven B Mwenya**  
**Senior Aeronautical Information Services Officer (SAISO).**